

## Quick Start Guide Bluetooth Music Receiver WM-BT43

Compatible with the following models:

- **Audi RNS-E Navigation (Navigation Plus)**
- AUDI A3, A4 ,A6 (2004-2005), AUDI TT, AUDI R8, AUDI A8 (2001-2002)
- Lamborghini Gallardo

### Connect the adapter:

1. Remove the radio (you will find various instructions on the internet).
2. Before disconnecting the plugs from the radio, make sure that the radio code is available to you as you will need it for the radio after the power cut.
3. Plug the gray AMP connector of the adapter into the port provided behind the radio.



4. Now connect the black earth cable to the radio housing or the black cable directly to a ground lead to the radio connection (usually brown thick cable). Without a good ground connection, the function of the adapter is not given.
5. Now connect the red cable (ignition plus + 12V) to a switched + 12V line. Since this is usually no longer available behind the radio you can pick up the voltage here, for example, from the cigarette lighter, fuse box (terminal 15) or the air conditioning (measurement with multimeter necessary). Ignition on = + 12V are on / Ignition off = 0V are on.
6. Establish a Bluetooth connection by enabling Bluetooth pairing and searching for the Bluetooth device ``WM``. You should then set the volume to full volume on the connected device.
7. Before reinstalling the radio, test the function of the adapter. To do this, turn on the radio's AUX function.

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	32 Pin AMP Connector											
16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1												
1	N. C.						8	N. C.								15	In-sync			22	AUX-NF-In-Left					29	NF-In-Left
2	N. C.						9	N. C.								16	In-G			23	N. C.					30	RGBS-In-GND
3	N. C.						10	N. C.								17	N. C.			24	N. C.					31	In-B
4	N. C.						11	N. C.								18	N. C.			25	N. C.					32	In-R
5	N. C.						12	N. C.								19	N. C.			26	N. C.						
6	AUX-NF-In-Right						13	NF-In-Right								20	N. C.			27	N. C.						
7	N. C.						14	SHIELD GND								21	AUX-NF-GND			28	NF-In-GND						

### For Info!

The AUX input on the radio must be unlocked. If AUX can not be selected, the activation in a specialist workshop is necessary.

Has something been left unclear? You can reach us MO-FR, from 8-17 o'clock under the E-Mail: [technik@watermark-germany.de](mailto:technik@watermark-germany.de)