

## Quick Start Guide Bluetooth Music Receiver WM-BT38


Compatible with the following models:

- ALFA ROMEO 147, 156, 159, Brera, Mito, GT, Spider
- FIAT 500, Bravo year 2007 - 2014, Croma from year 2005, Doblo from year 2001, Ducato from year 2002, Idea from year 2004, Multipla from year 1999, Palio, Panda year 2004 - 2017, Punto 188 Bj. 1999 - 2007, Punto 199 from 2005, Punto Evo from Bj. 2009, Stilo from 2002
- LANCIA Musa, Ypsilon

### Connect the adapter:

1. Remove the radio (you will find various instructions on the internet).
2. Before disconnecting the plugs from the radio, make sure that the radio code is available to you as you will need it for the radio after the power cut.
3. Insert the yellow expander of the adapter into chamber C1 (countersigned with C1 in the picture).
4. If necessary, remove the yellow plug from the yellow-green-blue plug combination and attach the yellow plug of the WM-BT16 there instead.

If you have installed a black 20-pin connector in the vehicle, you will also need the adapter WM-4693 (mini-ISO adapter / extension). This can be ordered in our online shop at [www.watermark-germany.de](http://www.watermark-germany.de).



5. Now connect the black ground cable to the radio housing or the black cable directly to a ground lead to the radio connection (usually brown thick cable). Without a good ground connection, the function of the adapter is not given.
6. Now connect the red cable (ignition plus + 12V) to a switched + 12V line. Since this is usually no longer available behind the radio, you can pick up the voltage from the cigarette lighter or the air conditioning (measurement with multimeter necessary). Ignition on = + 12V are on / Ignition off = 0V are on.
7. Establish a Bluetooth connection by activating Bluetooth pairing and searching for the ``WM`` Bluetooth device. You should then set the volume to full volume on the connected device.
8. Before reinstalling the radio, test the function of the adapter. Turn on the AUX function with the CD / Mode button.

## **For Info!**

AUX must be unlocked and selectable on the radio. If this is not the case, activation in a specialist workshop is required.

Has something been left unclear? You can reach us MO-FR, from 8-17 o'clock  
the e-mail: [service@watermark-germany.de](mailto:service@watermark-germany.de)